



General Conformity Certification

Product Covered by Certificate	BIC Item Number	
BIC Classic Maxi Lighter	(See Attached List)	

<u>Place of Manufacture</u>	<u>Date of Manufacture</u>
Milford, CT Tarragona UNITED STATES SPAIN Redon Manaus FRANCE BRAZIL	Manufactured on or after November 12, 2008

<u>U.S. Importer</u>	<u>Record Keeper</u>
BIC USA Inc. One BIC Way, Suite 1 Shelton, CT 06484 203-783-2000	Product Safety Specialist One BIC Way, Suite 1 Shelton, CT 06484 Tele: 203-783-2000 Fax: 203-783-2108 productsafety@bicworld.com

<u>Regulation Description:</u>	<u>Regulation Citation:</u>	<u>Test Lab:</u>	<u>Test Date:</u>
Lighters subject to the Standard must be resistant to successful operation by children younger than five years of age.	Safety Standard for Cigarette Lighters 16 CFR Part 1210	Milford Consulting Associates 80 Ocean Avenue Milford, CT 06460 Contact: Gerald O. Cavallo, Ph.D. Managing Director Phone: (203) 876-0948 Fax: (203) 876-7530 e-mail: gcavallo@optonline.net	July 21-Aug 12, 2004

LC199	LCR199BAA	LCR199FTT	LCRT1UFC	LCWD1AM
LCP51	LCR199BBE	LCR199FVI	LCR199FPA	LCWT1NSD2
LC199W	LCR199BBR	LCXTR6A09	LCR199BOR	LC8KR17
LCP21	LCR199BCA	LR18WG07	LCR199FBL	LCPMW220
LCP172	LCR199BCO	LCZT50UD	LCEXT4	LCX199
LC199UP	LCR199BCR	LCZT50KG	LC0DS11	LOX37SM83
LCXT4FG05	LCR199BCU	LCR199FRA	LPH8WA37	LCRT1NSD
LCWA199	LCR199BDI	LCR199FIC	LOX46FB11	LCW6WM43
LCP51M	LCR199BDR	LCR199FEA	LCR199FRN	LCR199BRE
LCWT1AS	LCR199BIN	LCR199BWH	LCRT3NS	LCWT1MO
LCXT4DA08	LCR199BLA	LCWPMW216	LCR199FLI	LCXTR6A08
LCW7WM31	LCR199BOA	LC25SM20	LC24KR30	LCWT1AA
LCWT1TT	LCR199BOR	LCR199BCA	LOX8MC102	LCXT3DA08
LCWT1BIC	LCR199BPH	LG45SE35	LPH8MC28	LCW6WM42
LCXTR6F07	LCR199BPP	LOX38SM91	LCR199FSS	LCM7WG108
LCWB199	LCR199BRA	LCR199FSA	LBX28WA52	LCWPM120
LCWT1SS	LCR199BRE	LCR199FCB	LCR199FBI	LCZ199C
LCPS624WM	LCR199BSF	LCR199FFO	LBX28MC23	LCWR199
LCM7WG107	LCR199BSM	LCWT1LV	LCR199FDB	LCR199FCO
LCWT1FS	LCR199BTI	LC8DG87	LCR199BTI	LCPW56
LCWT1DS	LCR199BTW	LCZT50AE	LCR199BOA	LCP41BL
LCWH199	LCR199BWH	LCWT1JD	LCR199BCR	LCW6WM42
LCW6WM44	LCR199BYA	LOX37EM84	LCR199FDO	LCM7WG108
LCPW28M	LCR199BYM	LCR199FRE	LCR199FPN	LCWPM120
LCPMW51	LCR199FAF	LCR199BPH	LCPD112	LCZ199C
LCXT4	LCR199FBE	LCR199FGI	LC199SWTY	LCWR199
LCPW56M	LCR199FBI	LCR199FGJ	LCR199FJE	LCR199FCO
LCXT3FG05	LCR199FBL	LCRXT3NS	LCZT50JE	LCPW56
LCWP112	LCR199FBU	LCX8BI59	LCR199BPP	LCP41BL
LCXT3	LCR199FCA	LCXT3CP06	LCR199FTT	LCZT50AS
LCP21WM	LCR199FCB	LCR199FVI	LCR199FJA	LCZT50SO
LCPMW51M	LCR199FCH	LCWD1NR2	LCWT1AP	LCZT50TD
LCWP21	LCR199FCO	LCZT50EZ	LBX48MC13	LCX7MC13
LC8KR18	LCR199FDB	LYX98CM45	LCR199BTW	LCR199BCO
LCP21M	LCR199FDO	LCR199FBU	LCR199BSF	LCWPM2RNS
LCR199FEA	LCR199FSC	LS1WM06	LC3WM75	LC2WM76

LCR199FFO	LCR199BIN	LCPS624WMAAST		
LCR199FGI	LCWT1BR	LC6WM61		
LCR199FGJ	LCR199BYA	LC6WM62		
LCR199FHT	LC8DG86	LC6WM63		
LCR199FIC	LCR199FPT	LC6WM59		
LCR199FJA	LCX6MC55	LC6WM41		
LCR199FJE	LPH48SW38	LS6WM57		
LCR199FLI	LCR199FST			
LCR199FPA	LCPW28			
LCR199FPN	LCWT1SE			
LCR199FPT	LXY36BE07			
LCR199FRA	LCR199FBE			
LCR199FRE	LCR199BCU			
LCR199FRN	LCRT1DT			
LCR199FSA	LCXT4DA07			
LCR199FSC	LCR199BYM			
LCR199FSR	LCPM212M			
LCR199FSS	LQ8AD36			
LCR199FST	LCT25LC			
LCR199BLA	LCP51L			
LCX7SW34	LCPMW51L			
LCR199FSR	LCPW56L			
LPH48SW55	LCLCP11			
LCR199FCH	LCLCPM116			
LCX7SW41	LCRPM2NSD			
LCXT3DA07	LCRP2NSD			
LCXT3CP07	LC199UP6			
LCR199BSM	LCRT1RB			
LBX7SW52	LCWT1AC			
LCZT50CC	LCX9CT102			
LCR199BAA	LCWP212			
LCR199BMA	LCP6			
LE8WM10	LMS4WM75			
LCWT1AC	LMS4WM82			