



General Conformity Certification

Product Covered by Certificate	BIC Item Number	
BIC Classic Maxi Lighter	LTR (See Attached List)	

<u>Place of Manufacture</u>	<u>Date of Manufacture</u>
Milford, CT Tarragona UNITED STATES SPAIN Redon Manaus FRANCE BRAZIL	Manufactured on or after November 12, 2008

<u>U.S. Importer</u>	<u>Record Keeper</u>
BIC Graphic USA A division of BIC USA Inc. 14421 Myerlake Circle Clearwater, FL 33760 727-536-7895	Product Safety Specialist One BIC Way, Suite 1 Shelton, CT 06484 Tele: 203-783-2000 Fax: 203-783-2108 productsafety@bicworld.com

<u>Regulation Description:</u>	<u>Regulation Citation:</u>	<u>Test Lab:</u>	<u>Test Date:</u>
Lighters subject to the Standard must be resistant to successful operation by children younger than five years of age.	Safety Standard for Cigarette Lighters 16 CFR Part 1210	Milford Consulting Associates 80 Ocean Avenue Milford, CT 06460 Contact: Gerald O. Cavallo, Ph.D. Managing Director Phone: (203) 876-0948 Fax: (203) 876-7530 e-mail: gcavallo@optonline.net	July 21-Aug 12, 2004

LC199	LCR199BAA	LCR199FTT	LCRTIUFC	LCWDIAM
LCP51	LCR199BBE	LCR199FVI	LCR199FPA	LCWTINSD2
LC199W	LCR199BBR	LCXTR6A09	LCR199BOR	LC8KR17
LCP21	LCR199BCA	LR18WG07	LCR199FBL	LCPMW220
LCP172	LCR199BCO	LCZT50UD	LCEXT4	LCX199
LC199UP	LCR199BCR	LCZT50KG	LCODSII	LOX37SM83
LCXT4FG05	LCR199BCU	LCR199FRA	LPH8WA37	LCRTINSD
LCWA199	LCR199BDI	LCR199FIC	LOX46FBII	LCW6WM43
LCP51M	LCR199BDR	LCR199FEA	LCR199FRN	LCR199BRE
LCWTIAS	LCR199BIN	LCR199BWH	LCRT3NS	LCWTIMO
LCXT4DA08	LCR199BLA	LCWPMW216	LCR199FLI	LCXTR6A08
LCW7WM31	LCR199BOA	LC25SM20	LC24KR30	LCWTIAA
LCWTITT	LCR199BOR	LCR199BCA	LOX8MCI02	LCXT3DA08
LCWTIBIC	LCR199BPH	LG45SE35	LPH8MC28	LCW6WM42
LCXTR6F07	LCR199BPP	LOX38SM91	LCR199FSS	LCM7WGI08
LCWB199	LCR199BRA	LCR199FSA	LBX28WA52	LCWPM120
LCWTISS	LCR199BRE	LCR199FCB	LCR199FBI	LCZ199C
LCPS624WM	LCR199BSF	LCR199FFO	LBX28MC23	LCWR199
LCM7WGI07	LCR199BSM	LCWTILV	LCR199FDB	LCR199FCO
LCWTIFS	LCR199BTI	LC8DG87	LCR199BTI	LCPW56
LCWTIDS	LCR199BTW	LCZT50AE	LCR199BOA	LCP41BL
LCWH199	LCR199BWH	LCWTIJD	LCR199BCR	LCW6WM42
LCW6WM44	LCR199BYA	LOX37EM84	LCR199FDO	LCM7WGI08
LCPW28M	LCR199BYM	LCR199FRE	LCR199FPN	LCWPM120
LCPMW51	LCR199FAF	LCR199BPH	LCPD112	LCZ199C
LCXT4	LCR199FBE	LCR199FGI	LC199SWTY	LCWR199
LCPW56M	LCR199FBI	LCR199FGJ	LCR199FJE	LCR199FCO
LCXT3FG05	LCR199FBL	LCRXT3NS	LCZT50JE	LCPW56
LCWP112	LCR199FBU	LCX8BI59	LCR199BPP	LCP41BL
LCXT3	LCR199FCA	LCXT3CP06	LCR199FTT	LCZT50AS
LCP21WM	LCR199FCB	LCR199FVI	LCR199FJA	LCZT50S0
LCPMW51M	LCR199FCH	LCWDINR2	LCWTIAP	LCZT50TD
LCWP21	LCR199FCO	LCZT50EZ	LBX48MC13	LCX7MC13
LC8KR18	LCR199FDB	LYX98CM45	LCR199BTW	LCR199BCO
LCP21M	LCR199FDO	LCR199FBU	LCR199BSF	LCWPM2RNS
LCR199FFO	LCR199BIN	LCR199FGI	LCWTIBR	LCWTIAC

LCR199FJE	LPH48SW38
LCR199FLI	LCR199FST
LCR199FPA	LCPW28
LCR199FPN	LCWTISE
LCR199FPT	LXY36BE07
LCR199FRA	LCR199FBE
LCR199FRE	LCR199BCU
LCR199FRN	LCRTIDT
LCR199FSA	LCXT4DA07
LCR199FSC	LCR199BYM
LCR199FSR	LCPM212M
LCR199FSS	LQ8AD36
LCR199FST	LCT25LC
LCR199BLA	LCP51L
LCX7SW34	LCPMW51L
LCR199FSR	LCPW56L
LPH48SW55	LCLCPII
LCR199FCH	LCLCPMI16
LCX7SW41	LCRPM2NSD
LCXT3DA07	LCRP2NSD
LCXT3CP07	LCX6MC55
LCR199BSM	LCR199FJA
LBX7SW52	LCR199FIC
LCZT50CC	LCR199FPT
LCR199BAA	DCLTR
LCR199BMA	
LE8WMIO	